Weathertzstion Assistance

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/90009MD2636/1

Work Order Type: Weatherization

Audit Name: 2636

CLIENT INFORMATION

Client ID: 90009MD2636

<u>AGENCY INFORMATION</u>

Agency: Metropolitan Development and Housing Agency

Agency Phone: (615) 252-8500

Address: 701 South Sixth Street Fax: (615) 252-8533

Nashville, TN 37206 *Email Address:*

Company Name & License Number:	
Contractor's Signature:	

COMMENT

AUDIT CONDUCTED 4PM-6:15PM 3/20/2012 TIMOTHY KEY 615-330-4785

Client ID: 90009MD2636

CONTRACTOR IS RESPONSIBLE FOR VERIFIYING ALL MEASUREMENTS ALL WEATHERIZATION MEASURES AND REPAIRS MUST BE DONE FOLLOWING THE SOUTHEAST FIELD GUIDE

CERTITFIED FIRM/RENOVATOR REQUIRED IF HOME BUILT PRIOR TO 1978

Measures

	Measure 1 TUN	EUP/SERVICE AC UNIT	Г		Componen	ts		1	nspected
C	omment 11/93 YI	EAR MANUFACTORED							
					Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					
c	Other Detail								
Ĺ									
_				Measur	e Sub Total:			Sub Total:	
	Measure 2 Seal	Ducts			Componen	ts			nspected
		Ducts SEAL DUCTS. LVGRO	OM, BR1,		Componen HEN, BR2, B Estimated	ATH		I Actual	Inspected
С			OM, BR1,		HEN, BR2, B	ATH	Qty		Inspected
<i>C</i>	omment MASTIC	SEAL DUCTS. LVGRO		KITCH	HEN, BR2, B	ATH	Qty	Actual	
C # 10	omment MASTIC	SEAL DUCTS. LVGRO Description / Comment	Units	KITCH Qty	HEN, BR2, B	ATH	Qty	Actual	
C # 10	omment MASTIC Material / Labor Miscellaneous Su	SEAL DUCTS. LVGRO Description / Comment	Units	KITCH Qty	HEN, BR2, B	ATH	Qty	Actual	
C # 10	omment MASTIC Material / Labor Miscellaneous Su	SEAL DUCTS. LVGRO Description / Comment	Units	KITCH Qty	HEN, BR2, B	ATH	Qty	Actual	
C # 10	omment MASTIC Material / Labor Miscellaneous Su	SEAL DUCTS. LVGRO Description / Comment	Units Each	Qty 1	HEN, BR2, B	ATH		Actual	

Measure 3 Inf	iltration Redctn			Componen	its			Inspected
2. D2 / 3. SEA 4. SEA	REPLACE WS. SEAL JAN ADD WS AL AROUND DRYER VEN AL PLUMBING @ KITCHE AL AROUND ELETRIC PA	IT EN SINK						
				Estimated	<i>d</i>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous S	u Infiltration Reduction	Each	1					
Other Detail								
			Measur	e Sub Total:]	Sub Total:	
Field Notes:								
					. =.			
Measure 4 Flo	oor Ins. R-19 IST. ADD CRAWL DOOR	PLUS LO		Componen 22X24. Estimated			Actual	Inspected
		PLUS LO		22X24.		Qty		Inspected Total
Comment 12 JOI	Description / Comment Floor Insulation -		CKSET	22X24. Estimated	d	Qty	Actual	
Comment 12 JOI # Material / Labor	IST. ADD CRAWL DOOR Description / Comment	Units	CKSET Qty	22X24. Estimated	d	Qty	Actual	
Comment 12 JOI # Material / Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt -	Units	CKSET Qty	22X24. Estimated	d	Qty	Actual	
Comment 12 JOI # Material / Labor 1 Insulation	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19	Units SqFt	Qty 988	22X24. Estimated	d	Qty	Actual	
Comment 12 JOI # Material / Labor 1 Insulation	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	Units SqFt	Qty 988	22X24. Estimated	d	Qty	Actual	
Comment 12 JOI # Material / Labor 1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	Units SqFt	Qty 988	22X24. Estimated	d	Qty	Actual	
Comment 12 JOI # Material / Labor 1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	Units SqFt	Qty 988	22X24. Estimated	d	Qty	Actual	
Comment 12 JOI # Material / Labor 1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	Units SqFt SqFt	Qty 988 988	22X24. Estimated	d		Actual	
Comment 12 JOI # Material / Labor 1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	Units SqFt SqFt	Qty 988 988	Estimated Unit Cost	d		Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	Units SqFt SqFt	Qty 988 988	Estimated Unit Cost	d		Actual Unit Cost	

	: Ins. R-30			Componen	ts A1		-	nspected
Comment 5 INCH	EXIST. ADD 7 INCH 12	2 TOTAL	ADD L	OAM <i>Estimated</i>	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	988					
2 Labor	Attic Insulation - Cellulose, Blown - R-30	SqFt	988					
Other Detail						1		
			Measur	e Sub Total:]]	Sub Total:	
Measure 6 CO I	Monitor is Needed							
				Componen	ts		ı	nspected
				Componen Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected Total
	-	<i>Units</i> Each		Estimated	1	Qty	Actual	
1 Health and Safety	-		Qty	Estimated	1	Qty	Actual	
1 Health and Safety	CO monitor	Each	Qty 1	Estimated	1	Qty	Actual	
1 Health and Safety2 Labor	CO monitor	Each	Qty 1	Estimated	1	Qty	Actual	
 # Material / Labor 1 Health and Safety 2 Labor Other Detail 	CO monitor	Each Each	Qty 1 1	Estimated	1		Actual	

		mproper Venting (Cloth CE 5FT WITH FLEX HOS	-)	Componen	ts		ı	nspected
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Equipment	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail						1		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 8 Smo	ke Detector is Needed			Componen	ts		,	Inspected
		ke Detector is Needed			Componen Estimated			I Actual	Inspected
C		ke Detector is Needed Description / Comment	Units	Qty	•		Qty		Inspected
C	Comment Material / Labor		<i>Units</i> Each		Estimated	<u> </u>	Qty	Actual	
C # 1	Comment Material / Labor	Description / Comment		Qty	Estimated	<u> </u>	Qty	Actual	
c # 1	Comment Material / Labor Health and Safety	Description / Comment Smoke detector	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
C # 1	Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
c # 1	Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
C # 1	Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each Each	Qty 1 1	Estimated	<u> </u>		Actual	

	Measure 9 Vapor Barrier Needed (Basement/Crawlspace) 1288 SQ/I		88 SQ/FT		Componen	Inspected			
C	omment OVERL	AP 12" AND RUN UP WA	ALLS AND	PIER	12"				
				Estimated	1				
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Basement / crawlspace vapor barrier	SqFt	1					
2	Labor	Labor	SqFt	1					
C	Other Detail								
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
			Work O	rder Gra	and Total:		Gran	d Total:	